

T43T80





Ventilation gap must be present

* Min. 70 for all induction hobs integrated flush with surrounding surfaces

The line drawings are provided as a guide to general dimensions only and are subject to amendment without prior notice. For full dimensional and installation details please refer to the documentation supplied with the appliance.

